



Pennant Walters Ltd

Mynydd Glyn Wind Farm

Draft Environmental Statement

Appendix 12C Accident Data



This report was prepared by WSP Environment & Infrastructure Solutions UK Limited (formerly known as Wood Environment & Infrastructure Solutions UK Limited), company registration number 02190074, which is carrying out these services as a subcontractor and/or agent to Wood Group UK Limited

October 2022

2.02062+12	None	Fatal	Police officer attended crash scene	May 6, 2020	2020	4	2	305610	Rhonda, Cynon Taff	A423	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	Crossroads	Pedestrian phase at traffic signal junction	0	1	0	0	0	0	1	1	0	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-201962190045	301810	190025	
2.01962+12	None	Slight	Police officer attended crash scene	December 6, 2019	2019	1	1	302711	Rhonda, Cynon Taff	A405	Raining with high winds	Single carriageway	Wet or Damp	Daylight: regardless of presence of 40 streetlights	T or staggered junction	Pedestrian phase at traffic signal junction	0	0	1	0	0	0	0	0	1	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-201962190051	302711	190973	
2.01962+12	None	Slight	Police officer attended crash scene	April 21, 2019	2019	1	1	302667	Rhonda, Cynon Taff	A405	Raining without high winds	Dual carriageway	Wet or Damp	Daylight: regardless of presence of 40 streetlights	T or staggered junction	Pedestrian phase at traffic signal junction	0	0	0	0	0	0	0	1	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-201962190082	302667	190985		
2.01862+12	None	Serious	Police officer attended crash scene	July 30, 2018	2018	1	1	302723	Rhonda, Cynon Taff	A405	Other	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	T or staggered junction	Pedestrian phase at traffic signal junction	0	0	1	1	0	0	0	0	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-201862190093	302723	190962		
2.01762+12	None	Slight	Police officer attended crash scene	May 29, 2017	2017	2	1	302698	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Darkness: street lights 40 present and lit	T or staggered junction	Pedestrian phase at traffic signal junction	0	0	0	0	0	0	0	0	0	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-201762190093	302698	190976	
2.02062+12	None	Slight	Police officer attended crash scene	May 31, 2020	2020	1	1	304861	Merthyr Tydfil	A4102	Fine without high winds	Roundabout	Dry	Daylight: regardless of presence of 70 streetlights	Roundabout	No physical crossing facility within 50 metres	0	1	0	0	0	0	0	1	0	0	0	Merthyr Tydfil County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2020622000502	304861	200595	
2.01962+12	None	Slight	Police officer attended crash scene	August 29, 2019	2019	2	1	304858	Merthyr Tydfil	A470	Raining without high winds	Dual carriageway	Wet or Damp	Daylight: regardless of presence of 70 streetlights	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	Merthyr Tydfil County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621901143	304858	200548		
2.01862+12	None	Slight	Police officer attended crash scene	January 26, 2018	2018	1	1	304834	Merthyr Tydfil	A4102	Fine without high winds	Roundabout	Dry	Daylight: regardless of presence of 50 streetlights	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	Merthyr Tydfil County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2018621800114	304834	200541		
2.01762+12	None	Serious	No officer attended crash scene	February 4, 2017	2017	1	1	307822	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	Not at or within 20 metres of junction	Pelican, puffin, toucan or similar non-junction pedestrian light crossing	0	0	1	1	0	0	0	0	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700225	307822	189887	
2.01862+12	None	Slight	Police officer attended crash scene	August 31, 2018	2018	2	2	307617	Rhonda, Cynon Taff	A405	Fine without high winds	Dual carriageway	Dry	Daylight: regardless of presence of 30 streetlights	T or staggered junction	Pedestrian phase at traffic signal junction	0	0	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2018621800109	307617	189747	
2.01762+12	None	Slight	Police officer attended crash scene	February 4, 2017	2017	2	1	307193	Rhonda, Cynon Taff	A405	Raining without high winds	Dual carriageway	Wet or Damp	Daylight: regardless of presence of 30 streetlights	Multiple junction	Pedestrian phase at traffic signal junction	0	0	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700219	307193	189854	
2.01762+12	None	Serious	Police officer attended crash scene	March 16, 2017	2017	1	1	307197	Rhonda, Cynon Taff	A405	Fine without high winds	Dual carriageway	Dry	Daylight: regardless of presence of 30 streetlights	T or staggered junction	Pelican, puffin, toucan or similar non-junction pedestrian light crossing	0	0	1	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700431	307197	189838	
2.01762+12	None	Slight	Police officer attended crash scene	September 2, 2017	2017	1	2	307495	Rhonda, Cynon Taff	A405	Raining without high winds	Dual carriageway	Wet or Damp	Daylight: regardless of presence of 30 streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	1	1	0	0	0	0	0	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621701361	307495	189738	
2.01762+12	None	Serious	Police officer attended crash scene	December 21, 2017	2017	1	1	307191	Rhonda, Cynon Taff	A405	Raining without high winds	Dual carriageway	Wet or Damp	Darkness: street lights 30 present and lit	Crossroads	No physical crossing facility within 50 metres	0	0	1	0	0	0	0	0	0	0	0	Rhonda Cynon Taff County Borough	Auto traffic signal	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621701688	307191	189868	
2.01762+12	None	Serious	Police officer attended crash scene	December 12, 2017	2017	3	2	307240	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 40 streetlights	Not at or within 20 metres of junction	Pelican, puffin, toucan or similar non-junction pedestrian light crossing	0	0	0	0	0	0	1	1	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700113	307240	189790	
2.01762+12	None	Slight	Police officer attended crash scene	March 21, 2017	2017	3	2	306837	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	T or staggered junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	1	0	0	Rhonda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700544	306837	190176	
2.01962+12	None	Serious	Police officer attended crash scene	May 1, 2019	2019	1	1	305015	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Darkness: street lights 40 present but unit	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	1	0	0	0	0	0	1	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900582	305015	191032	
2.01962+12	None	Serious	Police officer attended crash scene	April 26, 2019	2019	2	1	305979	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Darkness: street lights 30 present and lit	T or staggered junction	Pelican, puffin, toucan or similar non-junction pedestrian light crossing	0	0	0	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900573	305979	190594
2.01962+12	None	Slight	Police officer attended crash scene	May 23, 2019	2019	1	1	306615	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Darkness: street lights 30 present and lit	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900712	306615	190833	
2.01962+12	None	Slight	Police officer attended crash scene	October 3, 2019	2019	2	2	305331	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 40 streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900274	305331	190914	
2.01762+12	None	Slight	Police officer attended crash scene	April 30, 2017	2017	2	1	304348	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	1	0	0	0	0	1	1	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700488	304348	190395	
2.01962+12	None	Slight	Police officer attended crash scene	October 1, 2019	2019	1	1	306812	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900189	306812	190316	
2.01962+12	None	Slight	Police officer attended crash scene	November 21, 2019	2019	2	2	305202	Merthyr Tydfil	A405	Raining without high winds	Single carriageway	Wet or Damp	Daylight: regardless of presence of 40 streetlights	T or staggered junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900525	305202	191026	
2.01962+12	None	Slight	Police officer attended crash scene	September 2, 2019	2019	2	1	304939	Rhonda, Cynon Taff	UO	Fine without high winds	Single carriageway	Wet or Damp	Daylight: regardless of presence of 40 streetlights	T or staggered junction	No physical crossing facility within 50 metres	0	1	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900153	304939	191028	
2.02062+12	None	Slight	Police officer attended crash scene	December 2, 2020	2020	2	1	305832	Rhonda, Cynon Taff	A405	Raining without high winds	Single carriageway	Wet or Damp	Daylight: regardless of presence of 30 streetlights	T or staggered junction	No physical crossing facility within 50 metres	1	0	0	0	1	0	0	1	0	0	1	Rhonda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2020622001061	305832	190705	
2.01762+12	None	Slight	Police officer attended crash scene	July 9, 2017	2017	1	1	305325	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Darkness: street lights 40 present but unit	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	1	0	0	0	0	0	1	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621701053	305325	190970	
2.01762+12	None	Slight	Police officer attended crash scene	May 2017	2017	3	2	305427	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	Using private drive or entrance	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700709	305427	190903	
2.01762+12	None	Slight	Police officer attended crash scene	May 20, 2017	2017	2	1	306319	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Wet or Damp	Daylight: regardless of presence of 30 streetlights	Not at or within 20 metres of junction	Pelican, puffin, toucan or similar non-junction pedestrian light crossing	1	0	0	1	1	0	1	0	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700790	306319	190937	
2.01762+12	None	Slight	Police officer attended crash scene	April 22, 2017	2017	1	1	306319	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Dry	Daylight: regardless of presence of 30 streetlights	Not at or within 20 metres of junction	Pelican, puffin, toucan or similar non-junction pedestrian light crossing	0	0	1	1	0	0	0	1	0	0	0	Rhonda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2017621700672	306319	190937	
2.01962+12	None	Slight	Police officer attended crash scene	February 2, 2019	2019	2	1	303711	Rhonda, Cynon Taff	A405	Fine without high winds	Single carriageway	Wet or Damp	Darkness: no street lighting	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	0	0	Rhonda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/prerep/orservice/ReportId-2019621900165	303711	191089
2.02062+12	None	Slight																																	



Validated Data

Data for South of the Route to the M4

Accident_ID	Carriageway_Hazards	Severity	Officer_Attended	Accident_DateTime	Year	Number_of_vehicles	Number_of_casualties	Eastings	Northings	Highway_Authority	Road_Number	Weather_conditions	Road_Type	Road_Surface	Speed_Limit	Light_conditions	Junction_detail	Pedestrian_Crossing	Involved_pe_dalycycle	Involved_Mo_torcycle	Pedestrian_casualty	Child_casualty	Pedal_casualty	Motorcycle_user_casualty	Involved_car	Involved_goodsvehicle	Involved_Bus	Involved_young_driver	Local_Authority_District	Junction_control	Is_Provisional	Is_Amended	Web_Link	X	Y	
2.02062E+12	None	Slight	Police officer attended crash scene	November 17, 2020	2020	1	1	303297	190934	Rhondda, Cynon, Taff	A4058	Raining with high winds	Single carriageway	Wet or Damp		Daylight: regardless of 30 presence of streetlights	T or staggered junction	Pelican, puffin, toucan or similar non-junction pedestrian light crossing	0	0	1	0	0	0	0	1	0	0	0	Rhondda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2020622001006	303297	190934
2.02062E+12	None	Slight	Police officer attended crash scene	July 4, 2020	2020	2	1	303313	190937	Rhondda, Cynon, Taff	A4058	Fine without high winds	Single carriageway	Wet or Damp		Daylight: regardless of 30 presence of streetlights	T or staggered junction	No physical crossing facility within 50 metres	1	0	0	0	0	1	0	0	1	0	0	Rhondda Cynon Taff County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2020622006062	303313	190937
2.01862E+12	None	Slight	Police officer attended crash scene	April 22, 2018	2018	1	1	303646	206641	Merthyr Tydfil	A4102	Fine without high winds	Roundabout	Dry		Daylight: regardless of 50 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	0	1	0	0	0	1	0	0	0	Merthyr Tydfil 1 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621800398	303646	206641	
2.01762E+12	None	Slight	Police officer attended crash scene	April 9, 2017	2017	2	1	303655	206699	Merthyr Tydfil	A4102	Fine without high winds	Roundabout	Dry		Daylight: regardless of 70 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	1	0	0	0	1	1	0	0	0	Merthyr Tydfil 1 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2017621700588	303655	206699	
2.01862E+12	None	Serious	Police officer attended crash scene	May 29, 2018	2018	1	1	303696	206689	Merthyr Tydfil	A4102	Fine without high winds	Roundabout	Dry		Darkness: street lights 30 present and lit	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	Merthyr Tydfil 0 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621800688	303696	206689	
2.01962E+12	None	Slight	Police officer attended crash scene	September 24, 2019	2019	4	3	303680	206624	Merthyr Tydfil	A4102	Raining without high winds	Roundabout	Wet or Damp		Daylight: regardless of 70 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	1	0	0	Merthyr Tydfil 0 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2019621901218	303680	206624	
2.01962E+12	None	Serious	Police officer attended crash scene	August 3, 2019	2019	2	2	304113	206086	Merthyr Tydfil	A470	Fine without high winds	Dual carriageway	Dry		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	Merthyr Tydfil 0 County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2019621901039	304113	206086	
2.01962E+12	None	Serious	Police officer attended crash scene	May 11, 2019	2019	2	2	304736	205192	Merthyr Tydfil	A470	Fine without high winds	Dual carriageway	Dry		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	0	0	0	Merthyr Tydfil 1 County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2019621900655	304736	205192	
2.01862E+12	None	Slight	Police officer attended crash scene	August 29, 2018	2018	1	1	303846	206450	Merthyr Tydfil	A470	Fine without high winds	Dual carriageway	Dry		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	Merthyr Tydfil 0 County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621801126	303846	206450	
2.01862E+12	None	Slight	Police officer attended crash scene	October 4, 2018	2018	3	1	304711	205208	Merthyr Tydfil	A470	Fine without high winds	Dual carriageway	Dry		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	Footbridge or subway	0	0	0	0	0	0	1	0	0	0	Merthyr Tydfil 1 County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621801279	304711	205208	
2.02062E+12	None	Slight	Police officer attended crash scene	April 28, 2020	2020	1	1	305033	204803	Merthyr Tydfil	A470	Raining without high winds	Dual carriageway	Wet or Damp		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	0	0	0	Merthyr Tydfil 0 County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2020622000442	305033	204803	
2.01762E+12	None	Slight	Police officer attended crash scene	April 2, 2017	2017	2	3	306060	203088	Merthyr Tydfil	A470	Fine without high winds	Roundabout	Dry		Daylight: regardless of 70 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	1	0	0	0	1	1	0	0	0	Merthyr Tydfil 0 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2017621700549	306060	203088	
2.01862E+12	None	Slight	Police officer attended crash scene	August 30, 2018	2018	2	1	306069	203096	Merthyr Tydfil	A470	Fine without high winds	Roundabout	Dry		Daylight: regardless of 60 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	1	0	0	0	1	1	0	0	0	Merthyr Tydfil 0 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621801093	306069	203096	
2.01862E+12	None	Slight	Police officer attended crash scene	May 15, 2018	2018	2	2	306060	203060	Merthyr Tydfil	A470	Fine without high winds	Roundabout	Dry		Daylight: regardless of 50 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	0	0	1	0	0	1	1	0	0	Merthyr Tydfil 0 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621800483	306060	203060	
2.01962E+12	None	Slight	Police officer attended crash scene	May 18, 2019	2019	2	1	302777	207806	Merthyr Tydfil	A470	Fine without high winds	Roundabout	Dry		Daylight: regardless of 60 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	1	0	0	0	1	1	0	0	0	Merthyr Tydfil 1 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2019621900676	302777	207806	
2.02062E+12	None	Slight	Police officer attended crash scene	March 9, 2020	2020	1	1	302772	207746	Merthyr Tydfil	A470	Raining with high winds	Roundabout	Wet or Damp		Daylight: regardless of 70 presence of streetlights	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	0	0	0	Merthyr Tydfil 0 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2020622000313	302772	207746	
2.02062E+12	None	Serious	Police officer attended crash scene	September 26, 2020	2020	1	5	302775	207793	Merthyr Tydfil	A465	Fine without high winds	Roundabout	Dry		Darkness: street lights 40 present and lit	Roundabout	No physical crossing facility within 50 metres	0	0	0	1	0	0	1	0	0	0	Merthyr Tydfil 0 County Borough	Give way or uncontrolled	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2020622000866	302775	207793	
2.02062E+12	None	Slight	Police officer attended crash scene	December 3, 2020	2020	1	1	303572	206868	Merthyr Tydfil	A470	Raining without high winds	Dual carriageway	Wet or Damp		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	0	0	0	Merthyr Tydfil 0 County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2020622001055	303572	206868	
2.01962E+12	None	Slight	Police officer attended crash scene	October 1, 2019	2019	4	3	308448	191652	Rhondda, Cynon, Taff	A470	Fine without high winds	Dual carriageway	Dry		Darkness: no street lighting	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	0	0	0	Rhondda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2019621901236	308448	191652	
2.01862E+12	None	Slight	Police officer attended crash scene	May 17, 2018	2018	3	1	308620	192161	Rhondda, Cynon, Taff	A470	Fine without high winds	Dual carriageway	Dry		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	1	0	0	Rhondda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621800480	308620	192161	
2.01762E+12	None	Serious	Police officer attended crash scene	May 9, 2017	2017	2	1	308649	193017	Rhondda, Cynon, Taff	A470	Fine without high winds	Dual carriageway	Dry		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	1	0	0	Rhondda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2017621700721	308649	193017	
2.01762E+12	None	Slight	Police officer attended crash scene	October 10, 2017	2017	4	1	307903	190742	Rhondda, Cynon, Taff	A470	Fine without high winds	Dual carriageway	Wet or Damp		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	0	0	0	Rhondda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2017621701417	307903	190742	
2.01762E+12	None	Slight	Police officer attended crash scene	September 29, 2017	2017	2	1	307791	190660	Rhondda, Cynon, Taff	A470	Raining without high winds	Dual carriageway	Wet or Damp		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	1	0	0	Rhondda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2017621701380	307791	190660	
2.01762E+12	None	Slight	Police officer attended crash scene	March 5, 2017	2017	1	1	308475	193564	Rhondda, Cynon, Taff	A470	Raining with high winds	Dual carriageway	Wet or Damp		Darkness: street lights 70 present and lit	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	1	0	0	0	Rhondda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2017621700394	308475	193564	
2.01862E+12	None	Slight	Police officer attended crash scene	October 3, 2018	2018	2	1	308579	193181	Rhondda, Cynon, Taff	A470	Fine without high winds	Dual carriageway	Dry		Daylight: regardless of 70 presence of streetlights	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	1	0	0	0	1	0	1	0	0	Rhondda Cynon Taff County Borough	Not Applicable	No	No	https://www.crashmap.co.uk/reports/proreport/service?reportid=2018621801274	308579	193181	

Department for Transport data published by www.crashmap.co.uk

